



## Modifications for V1.3

- **5V compatible I<sup>2</sup>C pads**
- **Pipeamp fix (sticky charge)**
  - ⇒ simulation with delayed clocks required
- **Daisy chain controller**
- **Power routing (FE, pipeamp, power pads)**
- **Comparator changes**
  - ⇒ has to be decoupled from analogue path
- **Overvoltage Problem**
  - ⇒ probably related to output driver
- **include DAC probe pads**
  - ⇒ perform PSSR measurement